




Description of sight line/obstruction:
 When stopped at the intersection I can see in an eastern direction to the driveway for H/No 58, this is approximately 85 metres.

When vehicles park on the opposite side of the road near the bend it significantly reduces this distance.

Description of sight line/obstruction:
 When stopped at the intersection I can see in an western direction to the power pole fronting H/No 69, this is approximately 140 metres.

However, if the tree is not pruned regularly I can only see approximately 20 metres. Google street view does not show it, but the tree currently is overgrown.



Description of reference points:

The attached image shows the location of the reference points and the location of the obstructions.

Yellow line = cars
 Crosses = reference point
 Tree = Blue shape

ADDITIONAL INFORMATION:

(Insert any additional information you believe may help us investigate the situation)

LOCATION DETAILS:

INTERSECTION OF (INSERT ROADS), (INSERT SUBURB)

CUSTOMER DETAILS:

CUSTOMER ADDRESS:

DATE: